

SEE

SHEET




N^o 2.

5

ADAMS

E. BAMBERGER
PLANING MILL

JULY 1890
FREEPORT
ILL.






N^o 4.

CLARK
AV.

CLAY

MECHANIC

J. B. MALLORY
CREMERY



SHEET




EXCHANGE

STEPHENSON

SHEET

CHICAGO

J. KLINE
CARRIAGE M^s




SEE

SEE


VAN BUREN

SHEET

N^o 8.



SEE



SEE